

Confidential Report

Our Ref: 23/61562F1/11/23





subcontracted test, UKAS accredited

** subcontracted test, EN ISO/IEC 17025 accredited

*** not UKAS accredited

Note: This report relates only to the items tested.

Shirley® Technologies Limited. Registered Office: Wira House, West Park Ring Road, Leeds, LS16 6QL. A company registered in England & Wales with company number 04669651. VAT Number GB 816764800. BTTG® and Shirley® are trade names of Shirley Technologies Ltd. The supply of all goods and services is subject to our standard terms of business, copies of which are available on request. Our laboratories are accredited to EN ISO/IEC 17025.

KAS



Wira House, West Park Ring Road, Leeds, LS16 6QL, UK. Telephone: +44 (0) 113 259 1999 Email: <u>onestopshop@bttg.co.uk</u> Website: <u>www.bttg.co.uk</u>

24 November 2023	Date:
23/61562F1/11/23 	Our Ref: Your Ref:
2 of 4	Page:

Client:

Thesign AG

Testing BS 5852: Clause 11: 2006 (2011) Assessment of the ignitability of upholstered seating by Smouldering and Flaming sources – Source 5 (Crib 5)

Pre-Treatment

The material received no pre-treatment as the fabric is stated not to be FR treated.

Conditioning

The sample was conditioned in the environments specified in Clause 10 of BS 5852: 2006 (2011).

Testing

The material was tested according to BS 5852:2006 (2011) Methods of test for the ignitability of upholstered composites for seating by flaming sources using Source 5 (Crib 5).

The sample was tested at 19°C and 61% relative humidity (R.H.).

The sample was tested over combustion modified polyurethane foam with a density of approximately 34-36kg/m³.





Wira House, West Park Ring Road, Leeds, LS16 6QL, UK. Telephone: +44 (0) 113 259 1999 Email: <u>onestopshop@bttg.co.uk</u> Website: <u>www.bttg.co.uk</u>

24 November 2023	Date:
23/61562F1/11/23 	Our Ref: Your Ref:
3 of 4	Page:

Client:

Thesign AG

Results

The following test results relate only to the ignitability of the combination of upholstery composites under the particular conditions of test stated; they are not intended as a means of assessing the full potential fire hazard of the materials or products in use.

	Specimen 1
Time of Ignition (mins/secs)	0.14
Time of Flame Extinction (mins/secs)	>8.51 ME
Time of Smoke Extinction (mins/secs)	>8.51 ME
Time of cover split (mins/secs)	2.51
Extent of damage (mm) - Seat	
Width	437 BTE
Length	283
Depth	42
Extent of damage (mm) - Back	
Width	>450 BTE
Depth	59
Melting	No
Dripping	No
Charring	Yes
Comments and Observations	ME/BTE
Specimen Result (Ignition or Non-ignition)	Ignition

Acronyms

ME – Manually extinguished DNO – Did not observe time of events

EC – Escalating combustion BTT – Burnt through thickness of foam DNS – Material did not split BTE – Burnt to extremities



Shirley® Technologies Limited. Registered Office: Wira House, West Park Ring Road, Leeds, LS16 6QL. A company registered in England & Wales with company number 04669651. VAT Number GB 816764800. BTTG® and Shirley® are trade names of Shirley Technologies Ltd. The supply of all goods and services is subject to our standard terms of business, copies of which are available on request. Our laboratories are accredited to EN ISO/IEC 17025.



Wira House, West Park Ring Road, Leeds, LS16 6QL, UK. Telephone: +44 (0) 113 259 1999 Email: <u>onestopshop@bttg.co.uk</u> Website: <u>www.bttg.co.uk</u>

24 November 2023	Date:
23/61562F1/11/23 	Our Ref: Your Ref:
4 of 4	Page:

Client:

Thesign AG

Comment

The results indicate 'Ignition' of the materials and the test is designated I/5 (ie. Fail).

Where required to make a judgement to any pass/fail criteria an estimation of uncertainty of measurement has been taken into account. Under our Policy we have used a non-binary decision rule.

See our decision rules Policy (<u>https://www.bttg.co.uk/about-us/decision-rules-policy/</u>) for further information.

Uncertainty Budget

Measurements: ± 2 mm Timings: ± 2 seconds

Reported by:.....

..... R Greasley, Laboratory Technician

...... B Bland, Technical Customer Service Officer Countersigned by:....

Enquiries concerning this report should be addressed to Customer Services.

