

Confidential Report

Our Ref: 23/61562D1/11/23







Telephone: +44 (0) 113 259 1999 Email: onestopshop@bttg.co.uk

Website: www.bttg.co.uk

Date: 24 November 2023

Our Ref: 23/61562D1/11/23

Your Ref: -

Page: 1 of 4

Client: Thesign AG

thesign SIAG Heimtextillen AG Neuseeland 32 CH-9404 Rorschacherberg Switzerland

Job Title: Fire Test on One Fabric Sample

Clients Order Ref: --

Date of Receipt: 14 November 2023

Date Test Started: 21 November 2023

Description of Sample: One sample of fabric, which was referenced by the client as;

Opus Velvet - 30700

Work Requested: We were asked to make the following fire test:

BS 5852: Clause 11:2006 (2011)

- * subcontracted test, UKAS accredited
- ** subcontracted test, EN ISO/IEC 17025 accredited
- *** not UKAS accredited



Note: This report relates only to the items tested.

Shirley® Technologies Limited. Registered Office: Wira House, West Park Ring Road, Leeds, LS16 6QL.

A company registered in England & Wales with company number 04669651. VAT Number GB 816764800.

BTTG® and Shirley® are trade names of Shirley Technologies Ltd.

The supply of all goods and services is subject to our standard terms of business, copies of which are available on request.

Our laboratories are accredited to EN ISO/IEC 17025.





Page:

Telephone: +44 (0) 113 259 1999 Email: onestopshop@bttg.co.uk

Website: www.bttg.co.uk

Date: 24 November 2023

Our Ref: 23/61562D1/11/23 Your Ref: ---

2 of 4

Client: Thesign AG

Testing BS 5852: Clause 11: 2006 (2011) Assessment of the ignitability of upholstered seating by Smouldering and Flaming sources – Source 5 (Crib 5)

Pre-Treatment

The material received no pre-treatment as the fabric is stated not to be FR treated.

Conditioning

The sample was conditioned in the environments specified in Clause 10 of BS 5852: 2006 (2011).

Testing

The material was tested according to BS 5852:2006 (2011) Methods of test for the ignitability of upholstered composites for seating by flaming sources using Source 5 (Crib 5).

The sample was tested at 18°C and 49% relative humidity (R.H.).

The sample was tested over combustion modified polyurethane foam with a density of approximately 34-36kg/m³.







Telephone: +44 (0) 113 259 1999 Email: onestopshop@bttg.co.uk

Website: www.bttg.co.uk

24 November 2023 Date:

Our Ref: 23/61562D1/11/23 Your Ref:

> Page: 3 of 4

Client: **Thesign AG**

Results

The following test results relate only to the ignitability of the combination of upholstery composites under the particular conditions of test stated; they are not intended as a means of assessing the full potential fire hazard of the materials or products in use.

	Specimen 1	Specimen 2
Time of Ignition (mins/secs)	0.07	0.06
Time of Flame Extinction (mins/secs)	3.21	3.36
Time of Smoke Extinction (mins/secs)	8.19	8.26
Time of cover split (mins/secs)	0.19	0.12
Extent of damage (mm) - Seat		
Width	146	147
Length	107	128
Depth	60	69
Extent of damage (mm) - Back		
Width	96	111
Depth	54	55
Melting	Yes	Yes
Dripping	No	No
Charring	Yes	Yes
Comments and Observations		
Specimen Result (Ignition or Non-ignition)	Non-Ignition	Non-Ignition

Acronyms

ME – Manually extinguished DNO – Did not observe time of events EC – Escalating combustion BTT – Burnt through thickness of foam DNS - Material did not split BTE – Burnt to extremities







Telephone: +44 (0) 113 259 1999 Email: onestopshop@bttg.co.uk

Website: www.bttg.co.uk

24 November 2023 Date:

23/61562D1/11/23 Our Ref:

Your Ref:

Page: 4 of 4

Client: **Thesign AG**

Comment

The results indicate 'Non-Ignition' of the materials and the test is designated NI/5 (ie. Pass).

Where required to make a judgement to any pass/fail criteria an estimation of uncertainty of measurement has been taken into account. Under our Policy we have used a non-binary decision rule.

See our decision rules Policy (https://www.bttg.co.uk/about-us/decision-rules-policy/) for further information.

Uncertainty Budget

Measurements: ± 2 mm Timings: ± 2 seconds

Reported by:..... R Greasley, Laboratory Technician

...... B Bland, Technical Customer Service Officer Countersigned by:.....

Enquiries concerning this report should be addressed to Customer Services.



