

American Flamecoat inc.

520 Eagleton Downs Drive - D Pineville, NC 28134 O: 704.405.2550 F: 704.543.9772 www.americanflamecoat.com

March 10, 2022

thesign / AG NEUSEELAND 32 9404 RORSCHACHERBERG SWITZERLAND

Reference: Flammability Test Report: 102776

One (1) fabric sample identified as the sign/AG – FLAIR 10968 - treated with Flamecoat was received and tested in accordance with the California Technical Bulletin 117-2013, Section 1, Cover Fabric Test. The results are as follows:

<u>Test Results</u>Vertical Char Lengths4mm4mm3mm

The sample <u>meets</u> the requirements of the above standard. There were no ignitions or smoldering after 45 minutes on any of the three (3) specimens tested. In addition, none of the of the three test specimens displayed a char which was equal to or greater than 45mm.

If there are any questions or when we can be of further assistance, please let us know.

Sincerely,

Brad Souffrant President

